







INSTRUCCIONES DE ARMADO



A*16  40 mm	B*16  15 mm	C*24  8*40 mm	D*8  5*40 mm	E*3  2*4 mm	F*4  6*50 mm
G*8  6*30 mm	H*4 	J*2 	K*28  3.5*14 mm	L*16 	M*4 




1




2

A*2	B*2	C*1
40 mm	15 mm	8*40 mm




3


A*4	
	40 mm
B*4	
	15 mm




4

A*4	
	40 mm
B*4	
	15 mm

C*2	
	8*40 mm




5

C*4



8*40 mm





D*8

5*40 mm





6



E*3



9



10



K*16

3.5*14 mm

L*16