



NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS

A




X3

B




X3

C




X2

D




X2

E




X1

F




X1

G




X2

H




X2

I



X1

J



X1


K



M 6X35

X44


L



X1


1

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS




2

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS




3

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS




4

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS




5

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS




6

NOTE: 50% TIGHTEN BEFORE FIXING ALL BOLTS



7

NOTE:50% TIGHTEN BEFORE FIXING ALL BOLTS



8

NOTE:50% TIGHTEN BEFORE FIXING ALL BOLTS

